

Quality Control Standards for Method 1664 Oil & Grease

prepsmart



Quality control standards are critical to the validation of final results. Currently, quality control standard solutions for EPA Method 1664 are colorless. The addition of standards must be memorized or carefully tracked. In many cases, a limited quantity of sample is available, and if a mistake is made, it may be necessary to recollect and reanalyze the sample. This is costly and time consuming! **prepsmart** tinted standards provide visual verification of standard additions. In addition, the tint is pH indicating. With **prepsmart** standards, you will immediately see that the quality control standard has been added, and you can verify by the tint in the sample that it has been acidified.

Provides Significant Cost Savings:

- Eliminates Costly Standard Addition Errors
- Avoids Costly Re-preparation and Rework
- Increases Productivity
- Improves Quality

o2si
smart solutions

o2si is an ISO 9001 certified company.

Contact Daniel R. Biggerstaff, Ph.D.

(843) 763-4884

P.O. Box 30712 • Charleston, SC 29417

www.o2si.com

